



Case Study: Structure & Facilities Assessment. Location: Grangemouth.

Brief

IKM Consulting Ltd were appointed to provide specialist advice to a project team carrying out the demolition of a redundant facility at BP Grangemouth.

Solution

IKM's work included:

- Reviewing and identifying hazards, such as asbestos, chemical drums and residual product.
- Providing specialist health and safety advice.
- Preparing demolition contracts - highly detailed specification resulted in tenders within 10% of each other.
- Monitoring programmes for demolition work.
- **Reviewing condition of services prior to work commencing.**

Outcome

This potentially hazardous complex structure was safely demolished on time and on budget, with no lost time, accidents or impact on surrounding process units.



